

Document Ref.: RR Main Shaft G-8X SN101156-1

Project: Main Shaft G-8X SN101156-1 Date: January 2020

Author: J.M.C. Checked: J.J.C.

REFURBISHMENT REPORT OF MAIN SHAFT GAMESA G-8X



Serial number of front bearing	Serial number of rear bearing
support	support
GP040832	GP040833



INDEX

1	SCOPE	3
	INSPECTION AND WORKS CARRIED OUT	
3	CONCLUSIONS	6



1 SCOPE

The purpose of this document is to know the status of the Gamesa G-8X main shaft and the steps followed for refurbishment.

2 INSPECTION AND WORKS CARRIED OUT

The technical department has performed an inspection of the main shaft components after cleaning, determined that is not necessary to replace any component and proceeded to the refurbishment.

1. Opening of the covers and cleaning of the bearings.



2. Cleaning the points of corrosion and protection of the areas without paint.



RR Main shaft Gamesa G8X -CCR Wind Solar Consulting S.L.



3. Refilling of the bearings with grease SKF LG W M1.



4. Changing toric joints of the bearings covers.



5. Exterior sealing of the bearings covers.



RR Main shaft Gamesa G8X -CCR Wind Solar Consulting S.L.



5. Changing the breathers of the covers.



6. Shaft and bearing supports painted and areas not painted are protected.







3 CONCLUSIONS

The refurbishment is finished and the main shaft is ready for installation.

CCR Wind Solar Consulting S.L.

Ciudad del Transporte H1 - Sot 6 15890 Santiago de Compostela Spain

WEB: www.ccrwindsolar.com