



2012

Rapport blade 26463



Autor: Kader Benali

REDAK

Januari 2012

Location **Holland**
Blade type **: V52**

Turbine number:
Blade number **: 26612**
Service interval : **Blade inspection repair and repainted**
Service engineer : **Kader Benali**
Date **: 31-01-2012**



We cleaned the whole blade. After cleaning we sanded the blade.

After the sanding part we installed the blade inside the building, so we could repair the blade without difficult weather circumstances.





We put an extra wear and tear coating on the leading edge of the blade.



We painted the whole blade in ral 7035.




We have measured the lightning cable inside the blade with a Ohm measuring device.

The measure showed us that the cable is in good condition.



Blade type V52 25 m
Blade number 26463
Blade color Ral 7035



$\Omega m12$

$\Omega m12$

Lightning cable is not broken; both receptors showed 12 milliohms.